To: Hylton Jackson (Hylton.Jackson@dnr.iowa.gov)[Hylton.Jackson@dnr.iowa.gov]

Cc: Mitchell, Brian[Mitchell.Brian@epa.gov]

From: McCoy, Erin

Sent: Tue 6/7/2016 12:34:25 AM

Subject: FW: ERW-6 at Dico

Per Dico, the extraction well is back in operation (see below).



Erin McCoy, P.G. | Remedial Project Manager

EPA Region 7 | Superfund Division | Iowa Nebraska Branch

11201 Renner Blvd | Lenexa, KS 66219

Phone: 913.551.7977

mccoy.erin@epa.gov | www.epa.gov

From: Gts [mailto:gtsi2000@yahoo.com]
Sent: Monday, June 06, 2016 12:03 PM
To: McCoy, Erin < McCoy. Erin@epa.gov>

Subject: Re: ERW-6 at Dico

Well 6 is back in operation cleaned up and pumping

Sent from my iPhone

On Jun 3, 2016, at 10:02 AM, McCoy, Erin < McCoy. Erin@epa.gov > wrote:

Is the system still operational on the other 2 active ERW wells?

<image001.gif>Erin McCoy, P.G. | Remedial Project Manager

EPA Region 7 | Superfund Division | Iowa Nebraska Branch

11201 Renner Blvd | Lenexa, KS 66219

Phone: 913.551.7977

mccoy.erin@epa.gov | www.epa.gov

From: Mills, Brian (Safety) [mailto:brian.mills@titan-intl.com]

Sent: Friday, June 03, 2016 9:50 AM

To: McCoy, Erin < McCoy. Erin@epa.gov >

Cc: Gazi George (gtsi2000@yahoo.com) < gtsi2000@yahoo.com>

Subject: ERW-6 at Dico

Recently, extraction well #6 at Dico has had a significant reduction in flow rate. A well contractor has troubleshot the well to determine the cause of the reduction in flow rate.

The probable cause of the reduction in flow rate, is a buildup on the inside of the well pipe. The contractor will be removing the buildup from the inside of the well pipe and cleaning the well screen. The contractor should be able to get this extraction well back in operation on Monday.

Brian Mills

Consultant for Dico

Please Note: The information contained in this message may be privileged and confidential, protected from disclosure, and/or intended only for the use of the individual or entity named above. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any disclosure, distribution, copying or other dissemination of this communication is strictly prohibited. If you received this communication in error, please immediately reply to the sender, delete the message and destroy all copies of it. Any views or opinions expressed in this message are solely those of the individual sender, except where the sender specifies with authority them to be the views of Titan. Titan reserves the right to monitor both incoming and outgoing e-mails and therefore the sender and recipient of such e-mails should have no expectation of privacy in this regard. Thank You.